

# Connect the speed-regulating motor to the distribution box



## Overview

Connect the motor terminals U, V, and W to the contactor for power supply connection. Terminals 3 and 4 (the two thicker wires) should be connected to the excitation coil of the speed . In the fields of industrial automation and mechanical drive, speed regulating motors play a crucial role, and a correct understanding and mastery of the wiring diagram of speed regulating motors is the foundation for achieving their efficient and stable operation. In the following article, we will demonstrate how to wire and control a three-phase motor using VFD, external. In this video, I explain the start and stop wiring method for a VFD (Variable Frequency Drive) to control a motor. It is often used in industrial applications to control the speed of pumps, fans, and other motor-driven equipment. In a typical VFD electric motor setup, the VFD modulates the motor's input to achieve precise speed control.

## Article Content

Aug 29, 2025

Motor speed control

This page covers the speed control of electric motors, using two cascaded controllers for motor torque and motor speed control.

Dec 04, 2025

Electric winches MOTORBOX 150, 300 and 500 kg

8.4.2 - Connection Connect the power supply using the single-phase or three-phase male connector supplied and using about 0.5 m of power supply cable. Check that the winch works (direction of rotation)

May 15, 2026

How to Wire a Gearbox with an Electromagnetic Speed

To properly wire a gearbox with an electromagnetic speed control motor, follow the wiring method outlined below:

Apr 13, 2026

How to Work with the Speed Controller of the Diesel

In order to make users know more about the speed controller of diesel generator set, this paper introduces the working principle and wiring diagram of

Feb 12, 2026

PowerFlex 4M Adjustable Frequency AC Drive

Therefore, the filter must only be used in installations with grounded AC supply systems and be permanently installed and solidly grounded (bonded) to the building power distribution ground.

Jun 24, 2026

A diagram for wiring a variable frequency drive

Understanding the wiring diagram for a VFD is essential for proper installation and operation. The diagram illustrates the connections between the VFD, the motor,

Nov 28, 2025

How to Wire a VFD with Motor, PLC and External Devices

Wiring a Variable Frequency Drive (VFD) is a fundamental skill in industrial automation and control systems. As a modern component, it facilitates precise

Sep 19, 2025

### Wiring Diagram for Motor Controller: Simplified

Learn how to connect the wiring for a motor controller with the help of a detailed diagram. Step-by-step instructions provided.

Mar 06, 2026

### Speed regulator connected to speed regulating motor

Then connect the two AC ports of the speed regulating terminal to the single-phase 220V power supply, with the FG terminal as the grounding port. After connecting, turn on the power supply, turn on the

Apr 22, 2026

### Three-Phase Asynchronous Torque Motor Speed Controller Wiring

Want to wire a three-phase asynchronous torque motor speed controller? In this video, we provide a detailed wiring diagram and step-by-step instructions to help you set up your motor speed ...

Nov 02, 2025

### How to Wire a VFD with Motor, PLC and External Devices

Wiring a Three-Phase Motor and VFD The following power and control circuit diagram shows how to wire a VFD for speed control and changing the direction of

May 18, 2026

### Single Phase Motor Speed Controller Using

Single Phase Motor Speed Controller Using Potentiometer, 0-10V or RS485 Modbus RTU.: Hello friends in this video I have developed a single phase motor speed

Jun 19, 2026

### Speed Control of Three Phase Induction Motor

Speed control of three-phase induction motors plays an increasingly important application with modern industrial processes, both in efficient operation

May 21, 2026

### How to wire a VFD for motor control | VFD control wiring ...

In this video, I explain the start and stop wiring method for a VFD (Variable Frequency Drive) to control a motor. A VFD allows smooth motor control, reducing inrush current and improving...

Feb 05, 2026

## Understanding Variable-Speed Drive Wiring

Learn how to wire a variable speed drive using a comprehensive diagram and step-by-step instructions for easy installation and setup.

Oct 22, 2025

## Designing a Circuit Diagram for Controlling DC Motor

Learn how to build a DC motor speed controller circuit using a diagram and control the speed of your motors with precision.

Jan 30, 2026

## Variable Speed DC Motors, Under 1/3 to 1 hp (746 watts) 115/230

The Conveyor Controller supports both fixed and variable speed AC motors using 120/230/460 volts A.C., 50/60Hz, 1-3 Phase, and variable speed 90/180 volts D.C. motors (with 120/230 volts A.C.

May 23, 2026

## Jd1a-40 motor speed controller and how to connect the motor

Motor speed control method: The speed regulating motor is to change the speed of the motor by using the series, voltage, current, frequency and so on of the motor to make the thyristor voltage regulation

May 17, 2026

## Installation Manual, Bulletin 1395, Digital DC Drive, 1350A & 2250A

Bridge Output Connections - The output of the field bridge is connected to TB2-1 and -2 which in turn is connected to the field leads of the motor. The terminal labeled F+ on TB2 is connected to the F1 lead

Oct 25, 2025

## The Ultimate Guide to VFD Control Panel Wiring Diagrams

Learn how to wire a VFD control panel with a comprehensive diagram and step-by-step instructions. Understand the components and connections required for a

Jan 02, 2026

## VFD Electric Motor Control A Comprehensive Technical Guide

Variable Frequency Drives (VFDs) are electronic controllers that allow electric motors to run at variable speeds by adjusting the frequency and voltage of the power supplied to the motor. In a typical VFD

Jul 25, 2025

## Speed Regulation of Electric Motors: A Deeper Dive

Electric motors, crucial components in countless industrial and commercial applications, require precise control of their rotational speed for

Feb 11, 2026

## How to Connect a 3 Phase Motor in Star and Delta?

Learn how to connect a 3 phase motor in Star and Delta connection with the proper wiring steps, diagrams, voltage relations and current calculations

Jan 20, 2026

## Data-Sheet-Template-EN

This current is limited to 250A (200A over connector X2, 50A over connector X4) for PBX 190. Due to this, high input current it is necessary to choose the correct wire diameter to minimize voltage drop

## Contact Us

For more information, pricing, or custom solutions, please contact us:

Website: <https://elagage-lorrain.fr>

Email: [sales@elagage-lorrain.fr](mailto:sales@elagage-lorrain.fr)

Phone: +33 6 47 82 19 35

Address: 15 Rue de la République, 69002 Lyon, France

This document is for informational purposes only. Specifications subject to change without notice.

